



Building and Timber Pest Inspection Report

Inspection Date: Fri, 6 Feb 2026

Property Address: 6/33 Burke Rd, Malvern East VIC 3145,
Australia



Contents

	The Parties
Section A	Results of inspection - summary
Section B	General
Section C	Accessibility
Section D	Significant Items
Section E	Additional comments
Section F	Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report has been prepared in accordance with the pre-inspection agreement in place between the parties set out below, which set out the purpose and scope of the inspection, and the significant items that will be reported on. This Report reflects the opinion of the inspector based on the documents that have been provided. This Report should be read in its entirety and in the context of the agreed scope of Services. If there is a discrepancy between the summary findings and the body of the Report, the body of the Report will prevail. We recommend that you should promptly implement any recommendation or advice in this Report, including recommendations of further inspections by another specialist. If you have any queries with this Report or require further information, please do not hesitate to contact the person who carried out the inspection. This Report contains reference to material that is the copyright of Standards Australia reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

Original Inspection Date: Fri, 6 Feb 2026

Modified Date: Tue, 10 Feb 2026

The Parties

Name of the Client:

Name of the Principal(If Applicable):

Job Address: 6/33 Burke Rd, Malvern East VIC 3145, Australia

Client's Email Address:

Client's Phone Number:

Consultant: Andrew Lacey Ph: 0419 824 486
Email: Hawthorn@jimsbuildinginspections.com.au

Company Name: Jim's Building Inspections (Hawthorn)

Company Address and Postcode: Camberwell 3124

Company Email: Hawthorn@jimsbuildinginspections.com.au

Company Contact Numbers: 0419 824 486

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors

The following apply: N/A

Section A Results of Inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
Safety Hazard		✓
Major Defect		✓
Minor Defect	✓	
Live Timber Pest Activity		✓
Timber Pest Damage		✓
Conditions Conducive to Timber Pest Activity	✓	
Evidence of fungal decay activity and/or damage		✓
Evidence of wood borer activity and/or damage		✓
Evidence of a previous termite management program		✓

Overall Condition (Building)

In summary, the building, compared to others of similar age and construction is in good condition with some minor defects found.

Overall Condition (Timber Pest)

In summary, the building, compared to others of similar age and construction is moderate susceptibility to timber pest activity. Whilst no evidence of any termite activity or damage was noted, conditions conducive to timber pest activity were present.

Due to the construction type of the building, a successful chemical treatment may not be possible. Regular ongoing inspections should always be carried out especially to properties where successful chemical treatments may not be possible. Consultation with a pest control company is recommended to determine the best course of action.

Section B General

General description of the property

Building Type	Residential, Unit
Company or Strata title	Unknown
Floor	Slab on ground
Furnished	Furnished
No. of bedrooms	2
Occupied	Occupied
Orientation	South
Other Building Elements	Driveway, Garage, Party Walls
Other Timber Bldg Elements	Deck, Door Frames, Doors, External Joinery, Internal Joinery, Landscaping Timbers and Construction, Skirting Boards
Roof	Tiled, Pitched
Storeys	Single
Walls	Brick Veneer, Rendered
Weather	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior
- Interior
- Roof Exterior - Part
- Wall Exterior

The inspection excludes areas which are affected by obstructions, where access is limited or unsafe. We do not move obstructions and defects, timber pest activity or conditions conducive to these may not be obvious unless they are removed.

Inaccessible Areas

The following areas were inaccessible:

- Ceiling Cavity.
- Roof Exterior - Part
- Roof Void due to lack of access.
- Slab edge which would normally be exposed due to finished ground levels obscuring inspection.
- Wall exterior due to obstructions.
- Wall Exterior - where neighbouring buildings immediately adjoin.

Any areas which are inaccessible at the time of inspection present a high risk for undetected defects and timber pest activity and conditions conducive to these. The client is advised to make inaccessible areas accessible wherever possible for re-inspection.

Obstructions and Limitations

Building defects, termite and timber pest activity as well as conditions conducive to both, may be concealed by the following obstructions which prevented full inspection:

- Above safe working height
- Appliances and equipment

- Debris in gutters
- Decking
- Evidence of recently painted walls or ceilings
- External concrete or paving
- External finished ground level
- Fixed ceilings
- Fixed Furniture - Built-in Cabinetry
- Floor coverings
- Furniture
- Lack of suitable access or entry point
- Overhanging vegetation
- Stored items
- Vegetation
- Wallpaper or Wall Coverings

The presence of obstructions increases the risk of undetected building defects, timber pest activity and conditions conducive to these. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas urgently.

Undetected defect risk (Building)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: **Medium**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Undetected defect risk (Timber Pest)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: **Medium**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

Safety Hazard

No evidence was found

Major Defect

No evidence was found

Minor Defect

Finding 3.01

Building:

Location: Bathroom

Finding: Grout or sealant - Missing or degraded within the bathroom area

Information: It was noted on inspection that grout or sealant is degraded to areas within the bathroom.

Grout and sealants are used to keep the joint water tight and protective of all associated building materials.

Different materials move at different rates, generally causing cracking to grout at this point. Build up of moisture in the bathroom can also cause grout and sealants to degrade and become mouldy.

Any damaged or degraded materials should be scraped out and flexible and mould resistant materials should be applied to affected areas to prevent any subsequent water damage that may occur. Regular maintenance and replacement of damaged or missing grout/ sealant is highly recommended to the wet areas, as this is a regular wear and tear defect. Both grout and sealant in areas that come into regular contact with water should be maintained for the long term care of your property.

A bathroom specialist or tiling contractor should be appointed to complete these works as soon as possible.



Finding 3.02

Building:	
Location:	Bathroom
Finding:	Shower damp - Monitor
Information:	Damp is evident to the lower 400mm of wall to the shower alcove. There was no moisture noted higher up the wall nor in the wall of the wardrobe in the bedroom directly behind the shower area.

This defect is quite common, and is suspected to have been caused by moisture permeating or leaching through the grouting and perhaps gaps in the sealant.

Damp (or structural damp) refers to the presence of unwanted moisture in the structure of a building, either as the result of intrusion from outside, or condensation from within the structure. In the shower area, internal water leaks or other sources of excessive moisture are generally the cause of damp.

Unmanaged damp in the shower recess is likely to facilitate the formation and development of mould and fungi growth, decaying associated building materials and compromising their structural integrity. It is important to address damp conditions, as the World Health Organisation notes that excess moisture leads - on almost all indoor materials - to growth of microbes such as moulds, fungi and bacteria, which subsequently emit spores and other matter into the indoor air. Exposure to these contaminants is associated with a wide range of respiratory and other health-related

problems.

Monitoring the area is advised and if any visual signs of excessive moisture appear (peeling paint, mould) then consultation with a qualified plumber or bathroom specialist would be advised to identify the cause of damp and to perform remedial works as required.

Always ensure that sealant and grout is in good condition to prevent any moisture issues occurring in the future.



Finding 3.03

Building:


Location: Living Room
 Finding: Door - Stiff to slide
 Information: The door in this area was stiff and difficult to slide along the associated tracks at the time of the inspection. The door also appeared to be slightly loose within the frame.

Restricted function of the affected door may pose as a potential safety hazard if required for emergency egress from the building.

Generally, factors such as age of the building element and a lack of maintenance are the usual causes for this type of defect.

Cleaning of the tracks may improve the operation of the door. Replacement of door hardware or tracks may be required should the cleaning not be effective.

A door specialist or competent handyman may be engaged to perform this task.



Finding 3.04

Building:
 Location: Garage
 Finding: Cracking - Concrete flooring within garage - fine
 Information: Fine cracks were identified in the concrete flooring of the garage . Although fine cracks may be quite noticeable, they are only considered to be an appearance defect, and usually do not indicate any structural damage.

Generally the cause of a fine cracks in existing concrete paving such as driveways, garages and pathways is indicative of the expansion and contraction of the concrete. Such causes are generally due to environmental factors, such as moisture levels, weather conditions, root systems of nearby trees or the soil types on which they are laid.

Fine cracks may also be due to poor original installation of the concrete. Factors such as poor compaction of the sub surface and/or inadequate reinforcing of the slab may create cracking and other secondary defects.

Monitoring of all cracking should be conducted frequently. Always contact a building inspector should cracks widen, lengthen, or become more numerous.



Finding 3.05

Building:

Location:

Garage

Finding:

Inside of garage door showing signs of moisture staining to the base

Information:

At the time of inspection the inside of the garage door showed evidence of moisture staining at the base.

Doors should be sealed on all faces including top and bottom to prevent moisture seeping into the door structure and potentially causing secondary damage.

A suitably qualified handyman or painter may be engaged to inspect the door and re seal the door.



Finding 3.06

Building:

Location: Exterior walls - front

Finding: Fascia - Gaps between ends of boards

Information: The fascia boards around the outside of the property underneath the guttering had some gaps within it where the boards join. This can allow moisture to get into the ends of the boards and cause rotting to the timbers.

Early intervention and regular maintenance will prolong the useful life of these building elements.

It is advised that a qualified carpenter or competent handyman be engaged to inspect the fascia boards and seal the gaps where relevant. Failure to act on this defect may result in further deterioration of the property.





Finding 3.07

Building:

Location: All External Areas

Finding: Rendered wall - minor cracking

Information: Minor cracking to the rendered wall was identified at the time of inspection.


This type of cracking is often consistent with general movement of the foundations of the property and is not considered a major structural defect.

Whilst it is more of an appearance issue, repairs may be required as failure to act may allow moisture to enter the crack and cause secondary damage to other building elements.

Consultation with a suitably qualified renderer should be sought to determine costs involved with any repairs necessary.

Should cracks increase in size or number, speak with your building inspector for further advice.





moisture will not only cause rust and decay of the associated building materials, but can also provide conditions that are conducive to termite and timber pest activity. Blockages in gutters should therefore be removed immediately to ensure dry conditions are maintained.

It is highly advised that blocked gutters be cleared by the homeowner or a general handyperson as a matter of urgency. Failure to do so may result in moisture entering the property causing more significant damage.



Finding 3.09



Building:

Location: Roof Exterior
Finding: Weathered Roof tiles - fair condition but with some minor maintenance required
Information: Upon inspection of the exterior roofing, the majority of roof tiles were considered to be in a fair condition. While weathering of the tiles is consistent with the age of the property, some minor maintenance works are required.

Cracking of the mortar around the ridge and hip capping was noted. Tiles had shifted from their original positions allowing gaps underneath the tiles.

Repairs to the roof is required.

Consultation with a roofing contractor is advised to gain advice on remedial works that will be required . Where left unmanaged, damage can lead to a number of secondary defects, including water leaks and weather exposure to internal roofing structures.







Finding 3.10

Building:

Location: Roof Exterior

Finding: Trees - Overhanging and filling gutters

Information: At the time of inspection, it was noted the trees were overhanging the roof exterior . Overhanging trees often result in excessive amounts of leaf debris accumulating in gutters.

Gutters are a critical part of the building's management of storm water and rain. It is therefore important that they be kept clear to prevent secondary damage to associated building elements, including exterior and interior walls, ceiling linings and any adjoining building elements. Where gutters are blocked, pooling of rainwater is likely to occur, fast-tracking rust and corrosion of the roof plumbing elements.

It is highly advised that all overhanging tree branches be removed as soon as possible to prevent any further damage. An arborist may be engaged to perform this task.

Gutters should then be cleaned out by a gutter cleaning specialist. Repair and/or replacement of sections of damaged guttering may also be required where the extent of the damage necessitates.. Consultation with a licensed roof plumber will be required where guttering has been damaged.



Finding 3.11

Building:
Location: All Areas
Finding: Additional Photos - minor defects
Information: Additional photos are provided for your general reference. Arrows have been included where necessary to highlight areas of importance.



Live Timber Pest Activity

No evidence was found

Timber Pest Damage

No evidence was found

Conditions Conducive to Timber Pest Activity

Finding 6.01

Building:
Location: All External Areas
Finding: Building materials in direct ground contact - conducive to termites

Information: Where timber elements are in direct contact with the ground and consequently moisture or dampness, they become conducive to termite activity. Whether timber is used as a building element, part of a fencing structure or stored as an unused item, they can provide an environment that is attractive to termite infestation.

When met with excessive moisture, timber begins to decay and develop wood rot. Any timbers that are in direct contact with external grounds especially if left untreated or non-durable also provide ingress for subterranean termites into that particular element.

Where possible, the removal of any such materials that may be conducive to termite activity should be carried out as soon as possible to minimise the risk of termite attack. Where not possible or practical, regular monitoring of timber elements is recommended. Replacement of any damaged materials should be carried out where necessary.



Finding 6.02

Building: All External Areas
 Location: All External Areas
 Finding: Garden Beds - Conditions Conducive to Termites
 Information: Garden beds were found to be evident around and against the property. These garden beds can include untreated timber, and with a combination of moisture from

rainfall and hosing, can make conditions conducive to termite activity and termite ingress.

Plants against or very close to buildings can also provide cover/ shade and can provide an environment that is attractive to termite infestation.

The removal and replanting of species that do not provide "cover" or cutting back of existing vegetation will assist greatly in preventing this from occurring.

The removal of any such materials that may be conducive to termite activity should be carried out as soon as possible to minimize the risk of potential termite attack.



Finding 6.03

Building:	
Location:	Exterior walls - rear
Finding:	Overflows - Not plumbed for drainage
Information:	The overflows are not plumbed or connected to suitable drainage, which can result in the surrounding area becoming excessively damp.

These damp conditions can lead to secondary defects such as rot, rust or corrosion of associated building elements, the formation of fungal decay, or even the creation of potential slip hazards. When coupled with poor site drainage, pooling of water may also attract termite activity to this area.

It is highly recommended that a qualified plumber be appointed to install adequate drainage to the overflow or at least redirect it away from the edge of the house. These works will ensure that the area remains dry and free of any secondary defects.



Evidence of fungal decay activity and/or damage

No evidence was found

Evidence of wood borer activity and/or damage

No evidence was found

Section D Significant Items

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed

- As identified in summary and defect statements

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

- At the time of inspection, the property presented in a generally good condition when compared with properties of a similar age and a characteristic.

There were no major defects or urgent safety hazards noted – just a range of minor defects and maintenance items consistent with a property such as this.

In terms of the timber pest inspection, there was no evidence of any termite activity or damage. There were some conditions which would be classified as conducive to timber pest activity – those being timber building elements within in-ground contact, garden beds around the property, overflows not plumbed into stormwater drainage. No evidence of any previous chemical treatments were noted.

Details of all defects should be read in full within the body of the report. Action should be taken as per the recommendations listed within. Successfully ready to train with the storm AFL Adelaide campaign.

For further information, advice and clarification please contact Andrew Lacey on: 0419 824 486

Section D Significant Items

The following items were noted as - For your information

Noted Item

Building:
 Location: All Areas
 Finding: Termite inspection - no termite activity found
 Information: All areas of the dwelling are checked with particular attention paid to wet areas which were closely assessed to check for excessive levels of moisture and temperature anomalies.

No evidence of termite activity was found inside the property at the time of the inspection.

In an attempt to identify the presence of hidden timber pest activity, a variety of techniques are adopted to identify irregularities including, a moisture meter reading of susceptible areas, sounding of timber elements using a device called a "donga" visual assessment of materials affected by moisture or signs of deformity, trails and bridging constructed by termites, irregular and regular shaped holes in timber elements indicating pest destruction.

Termite activity generates high temperatures and moisture and if this irregularity is found it can be grounds for further investigation.

Wall paneling, wallpaper, carpet and fixed cabinetry can obscure termite activity.

Noted Item

Building:
 Location: All Areas
 Finding: Termite Management System - no evidence of a chemical installation
 Information: The application of a post-construction chemical termite barrier is highly recommended for all properties, particularly if live termite activity has been found on the site previously. Such barriers are highly effective in preventing termite attack on any timber building elements throughout the property.

A durable notice should be placed in the switchboard unit to indicate current termite barriers. At the time of inspection, it appeared as though no termite management system has been installed, with no evidence to suggest preventative works taking place.

The client may consider gaining further advice from a pest controller as to the costs and procedures involved with this application. It is recommended that obtaining such advice be a short-term priority.

Noted Item

Building:

Location: All Areas

Finding: Additional Photos for your information - bathroom door frame - gap on the side at the base

Information: At the time of inspection, it was noted that the bathroom door frame had a gap on the side at the base when the door was closed. It is unclear as to why this is present.

Whilst the door opened and closed as intended , the homeowner may wish to attend to the frame to ensure it seals correctly.




Noted Item

Building:

Location: All Areas

Finding: Additional Photos - Obstructions and Limitations

Information: These photographs are an indication of the obstructions and limitations which impeded full inspection of the property at the time of inspection. These obstructions can hide an array of defects and should be removed to allow full inspection to be carried out. A re-inspection is recommended once the areas are made accessible.









Definitions to help you better understand this report

Access hole (cover)	An opening in flooring or ceiling or other parts of a structure (such as service hatch, removable panel) to allow for entry to carry out an inspection, maintenance or repair.
Accessible area	An area of the site where sufficient, safe and reasonable access is available to allow inspection within the scope of the inspection.
Appearance defect	Fault or deviation from the intended appearance of a building element.
Asbestos-Containing Material (ACM)	Asbestos-containing material (ACM) means any material or thing that, as part of its design, contains asbestos.
Building element	A portion of a building that, by itself or in combination with other such parts, fulfils a characteristic function. NOTE: For example supporting, enclosing, furnishing or servicing building space.
Client	The person or other entity for whom the inspection is being carried out.
Conditions Conducive to Termite Activity	Noticeable building deficiencies or environmental factors that may contribute to the presence of Termites.
Defect	Fault or deviation from the intended condition of a material, assembly, or component.
Detailed assessment	An assessment by an accredited sampler to determine the extent and magnitude of methamphetamine contamination in a property.
Inspection	Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a reliable conclusion as to the condition of the building.
Inspector	Person or organisation responsible for carrying out the inspection.
Instrument Testing	Where appropriate the carrying out of Tests using the following techniques and instruments: (a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements (b) stethoscope - an instrument used to hear sounds made by termites within building elements (c) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g. bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees and (d) sounding - a technique where timber is tapped with a solid object. (e) T3I - an instrument used to detect movement, moisture and changes in temperature within timber
Limitation	Any factor that prevents full or proper inspection of the building.
Major defect	A defect of sufficient magnitude where rectification has to be carried

	out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
Methamphetamine	An amphetamine-type stimulant that is highly addictive. Methamphetamine is a controlled substance, classified as a Class A (very high-risk) drug under the Misuse of Drug Act. This term is used as a grouping term to include all substances screened for, specifically: Ephedrine, Pseudoephedrine, Amphetamine, Methamphetamine, MDA and MDMA.
Methamphetamine contamination	A property or part of a property where the level of methamphetamine has been tested in accordance with this standard and found to exceed 0.5 micrograms/100 cm ² (Residential) or 10 micrograms/100 cm ² (Commercial).
Methamphetamine production/manufacture	The manufacture of methamphetamine, including processing, packaging, and storage of methamphetamine and associated chemicals.
Minor defect	A defect other than a major defect.
Roof space/Roof void	Space between the roof covering and the ceiling immediately below the roof covering.
Screening assessment	An assessment by a screening sampler to determine whether or not methamphetamine is present.
Serviceability defect	Fault or deviation from the intended serviceability performance of a building element.
Significant item	An item that is to be reported in accordance with the scope of the inspection.
Site	Allotment of land on which a building stands or is to be erected.
Structural defect	Fault or deviation from the intended structural performance of a building element.
Structural element	Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.
Subfloor space	Space between the underside of a suspended floor and the ground.
Subterranean Termite Management Proposal	A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.
Termites	Wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.
Tests	Additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be

particularly susceptible to attack by Termites. Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.

Timber Pest Activity	Tell-tale signs associated with 'active' (live) and/or 'inactive' (absence of live) Timber Pests at the time of inspection.
Timber Pest Attack	Timber Pest Activity and/or Timber Pest Damage.
Timber Pest Damage	Noticeable impairments to the integrity of timber and other susceptible materials resulting from an attack by Timber Pests.
Urgent and Serious Safety Hazards	Building elements or situations that present a current or immediate potential threat of injury or disease to persons.

Terms on which this report was prepared

This report is based on the condition of the property at the time of inspection. We strongly recommend re-inspection 30 days after this report is issued as the general condition of the property is likely to have changed, including the extent of defects described and instance of potential undetected defects.

This report has been prepared in accordance with and subject to the pre-inspection agreement in place between the parties, which forms part of this Report.

This Report is prepared for the client identified above and may not be relied on by any other person without our express permission or by the purchase of this Report on our website.

SPECIAL ATTENTION SHOULD BE GIVEN TO THE SCOPE, LIMITATIONS AND EXCLUSIONS IN YOUR PRE-INSPECTION AGREEMENT AND THIS REPORT

Any of the exclusions or limitations identified for this Report may be the subject of a special-purpose inspection which we recommend being undertaken by an appropriately qualified inspector

RELIANCE AND DISCLOSURE

This report has been prepared based on conditions at the time of the report.

We own the copyright in this report and may make it available to third parties.

If your Property is in the Australian Capital Territory, you acknowledge we will make certain information about this Report available to the ACT Government for inclusion in the building and pest inspections public register if required under the *Civil Law (Sale of Residential Property) Act 2003*. This will include the fact the report has been prepared, the Property street address, date of the inspection, the name of the person who prepared the report and (if applicable) the entity that employs them.

UNDETECTED DEFECT RISK RATING

If this Report has identified a medium or high-risk rating for undetected defects, we strongly recommend a further inspection of areas that were inaccessible. This may include an invasive inspection that requires the removal or cutting of walls, floors or ceilings.

If the Property has been vacant for a period of time, moisture levels or leaks may not be detectable at the time of the inspection because often only frequent use of water pipes (showers, taps etc) result in a leak being identifiable. We advise further testing on pipes and water susceptible areas (such as the bathroom and laundry) after more frequent use has occurred.

IMPORTANT SAFETY INFORMATION:

This is not a report by a licensed plumber or electrician. We recommend a special-purpose

report to detect substandard or illegal plumbing and electrical work at the Property

This is not a smoke alarm report. We recommend all existing detectors in the Property be tested and advice sought as to the suitability of number, placement and operation.

This is not an asbestos report. There are potential products in the Property containing asbestos that will not be identified in this report. In order to accurately identify asbestos, we recommend performing an asbestos inspection, particularly for buildings built prior to 1988.

This is not a report on safety glass. Glazing in older homes may not reflect current standards and may cause significant injury if damaged. Exercise caution around the glass in older homes.

This is not a report on window opening restrictions. We have not inspected window opening restrictors. Window openings in older buildings may not reflect current standards and can be a potential risk. Window opening restrictors are advised for all second story or above windows with sill heights below 900mm. Some states make this a mandatory requirement. Owners should enquire of their local and state requirements to ensure compliance.

This is not a report on pool safety. If a swimming pool is present it should be the subject to a special purpose pool inspection.

External Timber Structures - Balcony and Decks. It is strongly recommended that a Structural Engineer is required to assess distributed load capacity of external timber structures such as balconies and decks, alerting users of the load capacity. Regular maintenance and inspections by competent practitioners to assess the ongoing durability of exposed external timber structures are needed.

This is not a Group Titled Property Report as per AS4349.2. If you require a report for a Group Titled Property as per this standard, please seek a separate inspection for Group Titled Properties.

MOISTURE

The identification of moisture, dampness or the evidence of water penetration is dependent on the weather conditions at the time an inspection. The absence of dampness identified in this Report does not necessarily mean the Property will not experience some damp problems in other weather conditions or that roofs, walls or wet areas are watertight.

Where the evidence of water penetration is identified we recommend detailed investigation of waterproofing in the surrounding area monitoring of the affected area over a period of time to fully detect and assess the cause of dampness.

MAINTENANCE OF THE PROPERTY

This Report is not a warranty or an insurance policy against problems developing with the Property in the future. Accordingly, a preventative maintenance program should be implemented which includes systematic inspections, detection and prevention of issues. Please contact the inspector who carried out this inspection for further advice.

It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of

conditions conducive to timber pest activity. Undertaking thorough regular inspections at intervals not exceeding twelve months (or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack). To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical barrier. However, AS3660 stresses that subterranean termites can bridge or breach barrier systems and inspection zones and those thorough regular inspections of the building are necessary.

NO CERTIFICATION

- a) The Property has been compared to others of a similar age, construction type and method that had an acceptable level of basic maintenance completed.
- b) We don't advise you about title, ownership or other legal matters like easements, restrictions, covenants and planning laws. None of our inspections constitutes approval by a Building Surveyor, a certificate of occupancy or compliance with any law, regulation or standard, including any comment on whether the Property complies with current Australian Standards, Building Regulations or other legislative requirements.

RECTIFICATION COSTS

We don't provide advice on the costs of rectification or repair unless specifically identified in the scope of the Report. Any cost advice provided verbally or in this report must be taken as of a general nature and is not to be relied on. Actual costs depend on the quality of materials, the standard of work, what price a contractor is prepared to do the work for and may be contingent on approvals, delays and unknown factors associated with third parties. No liability is accepted for costing advice.