



Building and Timber Pest Inspection Report

Inspection Date: Wed, 04 Mar 2026

Property Address: 10 Cadogan Cres, Woongarra NSW 2259,
Australia



Contents

	The Parties
Section A	Results of inspection - summary
Section B	General
Section C	Accessibility
Section D	Significant Items
Section E	Additional comments
Section F	Annexures to this report
	Definitions to help you better understand this report
	Terms on which this report was prepared
	Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report has been prepared in accordance with the pre-inspection agreement in place between the parties set out below, which set out the purpose and scope of the inspection, and the significant items that will be reported on.

This Report reflects the opinion of the inspector based on the documents that have been provided.

This Report should be read in its entirety and in the context of the agreed scope of Services. If there is a discrepancy between the summary findings and the body of the Report, the body of the Report will prevail.

We recommend that you should promptly implement any recommendation or advice in this Report, including recommendations of further inspections by another specialist.

If you have any queries with this Report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report contains reference to material that is the copyright of Standards Australia reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

Original Inspection Date Wed, 04 Mar 2026

Modified Date Wed, 04 Mar 2026

The Parties

Name of the Client:

Name of the Principal(If Applicable):

Job Address: 10 Cadogan Cres, Woongarra NSW 2259, Australia

Client's Email Address:

Client's Phone Number:

Consultant:

Company Name:

Company Address and Postcode:

Company Email:

Company Contact Numbers:

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors

The following apply: This report must be read in full and in conjunction with Section D5 – Assessment of the Overall Condition of the Property. The entire report should be reviewed to properly understand the findings, limitations, and context of the inspection.

The inspection and report reflect the condition of the property at the time of inspection only. Conditions

may change due to weather, occupancy, use, maintenance, or further deterioration. This report is valid for 90 days from the date of inspection. A re-inspection within 30 days is recommended, particularly where defects or elevated risk conditions have been identified.

This report focuses on the identification of safety hazards, major defects, and significant minor defects that may reasonably affect the property's condition, safety, serviceability, or value, or that may require repair, further investigation, or allowance in the foreseeable future. It is not an exhaustive list of all minor defects, cosmetic issues, or general wear and tear consistent with the age and use of the dwelling.

A non-invasive moisture meter was used as an auxiliary aid during the inspection. The instrument operates on a scale of 0–999, with readings above 200 considered elevated. Moisture readings are interpreted in conjunction with observable building condition and do not, on their own, confirm active leakage. As this was a visual, non-destructive inspection, concealed moisture-related damage may exist and cannot be ruled out.

A drone was used to assist with visual inspection of roof areas where safe physical access was limited. The inspection was visual only and did not allow confirmation of concealed components or fixings. Further close-access inspection may be required.

Any verbal advice provided before or after the inspection is general in nature and does not form part of this written report.

Section A Results of Inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
Safety Hazard		✓
Major Defect		✓
Minor Defect	✓	
Live Timber Pest Activity		✓
Timber Pest Damage		✓
Conditions Conducive to Timber Pest Activity	✓	
Evidence of fungal decay activity and/or damage		✓
Evidence of wood borer activity and/or damage		✓
Evidence of a previous termite management program		✓

Overall Condition (Building)

In summary, the building, compared to others of similar age and construction is in excellent condition

Overall Condition (Timber Pest)

In summary, the building, compared to others of similar age and construction is moderately susceptible to timber pests. A current termite treatment is in place. Minimum 12 monthly inspections should be carried out.

Section B General

General description of the property

Building Type	Detached, Residential
Company or Strata title	No
Floor	Slab on ground
Furnished	Furnished
Occupied	Occupied
No. of bedrooms	3
Orientation	South West
Other Building Elements	Driveway, Fence - Fabricated Metal Fence, Garage, Porch, Water Tanks
Other Timber Bldg Elements	Architraves, Door Frames, Doors, Eaves, Internal Joinery, Porch / Patio, Skirting Boards
Roof	Pitched, Tiled, Timber Framed
Storeys	Single
Walls	Brick Veneer
Weather	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior
- Interior
- Roof Exterior
- Roof Void - Part
- Wall Exterior

The inspection excludes areas which are affected by obstructions, where access is limited or unsafe. We do not move obstructions and defects, timber pest activity or conditions conducive to these may not be obvious unless they are removed.

Inaccessible Areas

The following areas were inaccessible:

- Ceiling Cavity - Part.
- Rooms where entry was denied to the inspector.
- Wall exterior due to obstructions.

Any areas which are inaccessible at the time of inspection present a high risk for undetected defects and timber pest activity and conditions conducive to these. The client is advised to make inaccessible areas accessible wherever possible for re-inspection.

Obstructions and Limitations

Building defects, termite and timber pest activity as well as conditions conducive to both, may be concealed by the following obstructions which prevented full inspection:

- Fixed Furniture - Built-in Cabinetry
- Fixed ceilings
- Floor coverings
- Furniture
- Insulation
- Roof framing - not trafficable
- Solar Panels
- Wall linings

The presence of obstructions increases the risk of undetected building defects, timber pest activity and conditions conducive to these. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas urgently.

Undetected defect risk (Building)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: - **Medium**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice

Undetected defect risk (Timber Pest)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: - **Medium**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice

Section D Significant Items

Safety Hazard

No evidence was found

Major Defect

No evidence was found

Minor Defect

Finding 3.01


Building: Main Building



Location: Bathroom, Ensuite

Finding: Deteriorated Shower Grout – Both Bathrooms

Information: Deterioration of the grout joints was observed within both shower enclosures. Sections of grout between floor tiles appear worn and are beginning to disintegrate in localized areas. Loss of grout reduces the integrity of the tiled surface as a moisture-resistant lining.

A tiler should be engaged to assess and rectify as required. This should be done as soon as practicable.





Finding 3.02


Building: Main Building

Location: Laundry

Finding: Toilet Flush Mechanism Malfunction – Laundry

Information: The dual-flush function to the toilet located in the laundry was observed not to be operating correctly at the time of inspection. Activation of the flush controls did not consistently engage the intended flush function. Faults within the flushing mechanism can affect the ability of the fixture to operate reliably and may lead to inefficient flushing performance or unnecessary water loss if the condition worsens.

A plumber should be engaged to assess and rectify as required. This should be done as soon as practicable.



Live Timber Pest Activity

No evidence was found

Timber Pest Damage

No evidence was found

Conditions Conducive to Timber Pest Activity

Finding 6.01

Building: Main Building

Location: Yard

Finding: Garden Beds - Conditions Conducive to Termites

Information: Garden beds, particularly those constructed from untreated timber, were noted adjacent to the dwelling. These create a highly conducive environment for termite activity due to the combination of retained soil moisture from watering, direct soil contact, and the organic material in the soil and timber edging. Such conditions increase the risk of concealed termite ingress into the property, as termites can travel through the garden beds and enter the structure undetected.

Where practical, garden beds should be removed, relocated, or modified so that they do not abut the dwelling. Where this is impractical or undesirable, the risk of concealed termite activity remains. In these cases, a licensed pest controller should establish an ongoing termite management plan, and regular timber pest inspections should be carried out every 6–12 months to assist in protecting the property against infestation.





Finding 6.02

Building: Main Building




Location: Yard

Finding: Bridging - Bridging of termite management system

Information: Bridging was observed at various locations around the external perimeter of the dwelling. Bridging occurs where materials or structures create a continuous path over or around the termite management system, allowing termites to bypass barriers and enter the dwelling undetected. Common examples include downpipes, fixed gates, hot water service units, air-conditioning units, garden beds, soil build-up, and paved surfaces installed hard against the slab or footing.

Bridging is a significant risk because it defeats the purpose of a physical or chemical termite barrier. Where practical, bridging elements should be modified or removed so that a clear and uninterrupted inspection zone remains around the entire perimeter.

Where it is not practical to remove or alter the bridging element, the risk of concealed termite entry remains. In these cases, a licensed pest controller should establish an ongoing termite management plan and carry out regular timber pest inspections every 6–12 months. This should be addressed without delay.



Finding 6.03

Building: Main Building
Location: Yard
Finding: Ground - Timber materials in direct ground contact

Information: Timber elements in direct contact with the ground, and consequently exposed to moisture or dampness, create conditions conducive to termite activity. Whether timber is used as part of a building structure, such as a fence or retaining wall, or stored as unused material, it can attract termite infestations.

When exposed to excessive moisture, timber begins to decay and develop wood rot. Any timber in direct contact with the ground - especially untreated or non-durable timber - provides an easy entry point for subterranean termites into the material.

To minimize the risk of termite attack, it is recommended to remove any materials that could foster termite activity. If removal is impractical or undesirable, it is strongly advised that termite or timber pest inspections be conducted every 6 to 12 months to protect the property from potential infestation.



Finding 6.04


Building: Main Building

Location: Meter Box

Finding: Durable Present - Durable notice observed in meter box

Information: A durable notice was observed in the meter box at the time of inspection, indicating that a termite management system has been installed at the property. The notice provides information on the type of system and treatment date, as required under AS 3660.1 and AS 3660.2.

While this confirms the presence of a past treatment, it does not verify the current effectiveness of the system. It is strongly advised that an ongoing termite management plan be established by a licensed pest controller. This should be addressed without delay.



Finding 6.05

Building: Main Building



Location: Yard - Back

Finding: Overflow - Appliance overflow discharging to ground

Information: At the time of inspection, the overflow from the A/C unit was observed to be discharging directly onto the ground rather than into a connected stormwater system. This could potentially result in damp conditions around the perimeter of the dwelling.

Sustained dampness in these areas is considered conducive to concealed termite activity and may also contribute to timber decay or pest infestation. A licensed plumber should be engaged to redirect the discharge into an appropriate drainage system. Rectification should be undertaken without delay.

Regular timber pest inspections should also be carried out every 6–12 months.



Evidence of fungal decay activity and/or damage

No evidence was found

Evidence of wood borer activity and/or damage

No evidence was found

Evidence of a previous termite management program

No evidence was found

Section D Significant Items

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed

- As identified in summary and defect statements
- Registered/Licensed Builder

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

The property was observed to be generally well presented and appears to have been reasonably maintained. The accessible areas of the dwelling were found to be in serviceable condition, with no significant structural concerns or major building defects identified during the inspection.

Only a small number of minor maintenance items were noted, primarily relating to routine upkeep of internal fixtures and tiled finishes. These items are typical of normal wear over time and are generally straightforward to address as part of ongoing property maintenance.

A small number of informational and monitoring observations have also been included in the report for purchaser awareness. These relate to isolated conditions that appeared stable at the time of inspection but have been recorded so they can be monitored as part of normal ownership.

Overall, the dwelling presents as a property that has been reasonably cared for, with the identified items not considered unusual for a home of this type.

For further information, advice and clarification please contact James Kerins on 0429 360 124

The following items were noted as -For your information


Noted Item


Building: Main Building



Location: All Areas

Finding: Additional Photos - Obstructions and Limitations

Information: These photographs are an indication of the obstructions and limitations which impeded full inspection of the property at the time of inspection. These obstructions can hide an array of defects and should be removed to allow full inspection to be carried out. A re-inspection is recommended once the areas are made accessible.







Noted Item


Building: Main Building


Location: Roof Void

Finding: Restricted Roof Void Access – Garage Roof Space

Information: The roof void is accessed via a personal access hatch located within the garage. Due to the configuration of roof framing members and trusses within the space, physical movement within the roof void was significantly restricted and inspection was limited to visual observation from the hatch opening only. As a result, portions of the roof void could not be directly accessed or inspected, and conditions within those concealed areas could not be determined during this inspection.

No immediate action is required; however, purchasers should be aware that areas of the roof space were not accessible for inspection due to framing configuration and access limitations.





Noted Item




Building: Main Building

Location: Living Room

Finding: Localised Elevated Moisture Reading – Living Room Wall

Information: A very high localised moisture meter reading was recorded to the wall surface within the living room, toward the left-hand side of the area inspected. The wall lining and surface finishes appeared visually sound at the time of inspection, with no staining, discoloration, distortion, or other visible material change observed. The source of the elevated reading could not be confirmed during this visual, non-invasive inspection.

This area should be monitored for any changes in the wall surface, particularly the development of discoloration or mould. If such changes occur, a licensed builder should be engaged to carry out further investigation as required.



Noted Item



Building: Main Building

Location: Dining Room

Finding: Localised Low-Level Elevated Moisture Reading – Dining Room Wall

Information: A slightly elevated moisture meter reading was recorded to a wall surface within the dining room. The wall lining and finishes appeared visually sound at the time of inspection, with no staining, discoloration, swelling, or other visible indication of moisture impact. The source of the elevated reading could not be confirmed during this visual, non-invasive inspection.

This area should be monitored for any changes in the wall surface, particularly the development of discoloration or mould. If such changes occur, a licensed builder should be engaged to carry out further investigation as required.



Noted Item

Building: Main Building

Location: Bedroom 2

Finding: Bedroom Not Fully Inspected – Occupied Room

Information: Access to one bedroom within the dwelling was available at the time of inspection; however, the room was occupied by a person sleeping in the bed. In order to avoid disturbing the occupant, the room was not entered and a full internal inspection of the space was not undertaken. From the doorway, a limited visual observation of the room was carried out, during which the visible wall surfaces, floor coverings, wardrobe, and window areas appeared generally consistent in condition with the remainder of the dwelling.

Due to the room not being fully accessed, the internal condition of all areas within this room could not be completely confirmed during this inspection. If confirmation of the condition of this room is required, the area should be made vacant and accessible for inspection. This should be done at the owner's discretion.



Definitions to help you better understand this report

Access hole (cover)	An opening in flooring or ceiling or other parts of a structure (such as service hatch, removable panel) to allow for entry to carry out an inspection, maintenance or repair.
Accessible area	An area of the site where sufficient, safe and reasonable access is available to allow inspection within the scope of the inspection.
Appearance defect	Fault or deviation from the intended appearance of a building element.
Asbestos-Containing Material (ACM)	Asbestos-containing material (ACM) means any material or thing that, as part of its design, contains asbestos.
Building element	A portion of a building that, by itself or in combination with other such parts, fulfils a characteristic function NOTE: For example supporting, enclosing, furnishing or servicing building space.
Client	The person or other entity for whom the inspection is being carried out.
Conditions Conducive to Termite Activity	Noticeable building deficiencies or environmental factors that may contribute to the presence of Termites.
Defect	Fault or deviation from the intended condition of a material, assembly, or component.
Detailed assessment	An assessment by an accredited sampler to determine the extent and magnitude of methamphetamine contamination in a property.
Inspection	Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a reliable conclusion as to the condition of the building.
Inspector	Person or organisation responsible for carrying out the inspection.
Instrument Testing	Where appropriate the carrying out of Tests using the following techniques and instruments: (a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements (b) stethoscope - an instrument used to hear sounds made by termites within building elements (c) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees and (d) sounding - a technique where timber is tapped with a solid object. (e) T3I - an instrument used to detect movement, moisture and changes in temperature within timber

Limitation	Any factor that prevents full or proper inspection of the building.
Major defect	A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
Methamphetamine	An amphetamine-type stimulant that is highly addictive Methamphetamine is a controlled substance, classified as a Class A (very high-risk) drug under the Misuse of Drug Act This term is used as a grouping term to include all substances screened for, specifically: Ephedrine, Pseudoephedrine, Amphetamine, Methamphetamine, MDA and MDMA.
Methamphetamine contamination	A property or part of a property where the level of methamphetamine has been tested in accordance with this standard and found to exceed 0.5 micrograms/100 cm ² (Residential) or 10 micrograms/100 cm ² (Commercial).
Methamphetamine production/manufacture	The manufacture of methamphetamine, including processing, packaging, and storage of methamphetamine and associated chemicals.
Minor defect	A defect other than a major defect.
Roof space/Roof void	Space between the roof covering and the ceiling immediately below the roof covering.
Screening assessment	An assessment by a screening sampler to determine whether or not methamphetamine is present.
Serviceability defect	Fault or deviation from the intended serviceability performance of a building element.
Significant item	An item that is to be reported in accordance with the scope of the inspection.
Site	Allotment of land on which a building stands or is to be erected.
Structural defect	Fault or deviation from the intended structural performance of a building element.
Structural element	Physically distinguishable part of a structure NOTE: For example wall, columns, beam, connection.
Subfloor space	Space between the underside of a suspended floor and the ground.
Subterranean Termite Management Proposal	A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.
Termites	Wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.

Tests	Additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be particularly susceptible to attack by Termites Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.
Timber Pest Activity	Tell-tale signs associated with 'active' (live) and/or 'inactive' (absence of live) Timber Pests at the time of inspection.
Timber Pest Attack	Timber Pest Activity and/or Timber Pest Damage.
Timber Pest Damage	Noticeable impairments to the integrity of timber and other susceptible materials resulting from an attack by Timber Pests.
Urgent and Serious Safety Hazards	Building elements or situations that present a current or immediate potential threat of injury or disease to persons.

Terms on which this report was prepared

This report is based on the condition of the property at the time of inspection. We strongly recommend re-inspection 30 days after this report is issued as the general condition of the property is likely to have changed, including the extent of defects described and instance of potential undetected defects.

This report has been prepared in accordance with and subject to the pre-inspection agreement in place between the parties, which forms part of this Report.

This Report is prepared for the client identified above and may not be relied on by any other person without our express permission or by the purchase of this Report on our website.

SPECIAL ATTENTION SHOULD BE GIVEN TO THE SCOPE, LIMITATIONS AND EXCLUSIONS IN YOUR PRE-INSPECTION AGREEMENT AND THIS REPORT

Any of the exclusions or limitations identified for this Report may be the subject of a special-purpose inspection which we recommend being undertaken by an appropriately qualified inspector

RELIANCE AND DISCLOSURE

This report has been prepared based on conditions at the time of the report.

We own the copyright in this report and may make it available to third parties.

If your Property is in the Australian Capital Territory, you acknowledge we will make certain information about this Report available to the ACT Government for inclusion in the building and pest inspections public register if required under the Civil Law (Sale of Residential Property) Act 2003. This will include the fact the report has been prepared, the Property street address, date of the inspection, the name of the person who prepared the report and (if applicable) the entity that employs them.

UNDETECTED DEFECT RISK RATING

If this Report has identified a medium or high-risk rating for undetected defects, we strongly recommend a further inspection of areas that were inaccessible. This may include an invasive inspection that requires the removal or cutting of walls, floors or ceilings.

If the Property has been vacant for a period of time, moisture levels or leaks may not be detectable at the time of the inspection because often only frequent use of water pipes (showers, taps etc) result in a leak being identifiable. We advise further testing on pipes and water susceptible areas (such as the bathroom and laundry) after more frequent use has occurred.

IMPORTANT SAFETY INFORMATION:

This is not a report by a licensed plumber or electrician. We recommend a special-purpose report to detect substandard or illegal plumbing and electrical work at the Property

This is not a smoke alarm report. We recommend all existing detectors in the Property be tested and advice sought as to the suitability of number, placement and operation.

This is not an asbestos report. There are potential products in the Property containing asbestos that will not be identified in this report. In order to accurately identify asbestos, we recommend performing an asbestos inspection, particularly for buildings built prior to 1988.

This is not a report on safety glass. Glazing in older homes may not reflect current standards and may cause significant injury if damaged. Exercise caution around the glass in older homes.

This is not a report on window opening restrictions. We have not inspected window opening restrictors. Window openings in older buildings may not reflect current standards and can be a potential risk. Window opening restrictors are advised for all second story or above windows with sill heights below 900mm. Some states make this a mandatory requirement. Owners should enquire of their local and state requirements to ensure compliance.

This is not a report on pool safety. If a swimming pool is present it should be the subject to a special purpose pool inspection.

External Timber Structures - Balcony and Decks. It is strongly recommended that a Structural Engineer is required to assess distributed load capacity of external timber structures such as balconies and decks, alerting users of the load capacity. Regular maintenance and inspections by competent practitioners to assess the ongoing durability of exposed external timber structures are needed.

This is not a Group Titled Property Report as per AS4349.2. If you require a report for a Group Titled Property as per this standard, please seek a separate inspection for Group Titled Properties.

MOISTURE

The identification of moisture, dampness or the evidence of water penetration is dependent on the weather conditions at the time an inspection. The absence of dampness identified in this Report does not necessarily mean the Property will not experience some damp problems in other weather conditions or that roofs, walls or wet areas are watertight.

Where the evidence of water penetration is identified we recommend detailed investigation of waterproofing in the surrounding area monitoring of the affected area over a period of time to fully detect and assess the cause of dampness.

MAINTENANCE OF THE PROPERTY

This Report is not a warranty or an insurance policy against problems developing with the Property in the future. Accordingly, a preventative maintenance program should be implemented which includes systematic inspections, detection and prevention of issues. Please contact the inspector who carried out this inspection for further advice.

It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of conditions conducive to timber pest activity. Undertaking thorough regular inspections at intervals not exceeding twelve months (or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack). To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical barrier. However, AS3660 stresses that subterranean termites can bridge or breach barrier systems and inspection zones and those thorough regular inspections of the building are necessary.

NO CERTIFICATION

a) The Property has been compared to others of a similar age, construction type and method that had an acceptable level of basic maintenance completed.

b) We don't advise you about title, ownership or other legal matters like easements, restrictions, covenants and planning laws. None of our inspections constitutes approval by a Building Surveyor, a certificate of occupancy or compliance with any law, regulation or standard, including any comment on whether the Property complies with current Australian Standards, Building Regulations or other legislative requirements.

RECTIFICATION COSTS

We don't provide advice on the costs of rectification or repair unless specifically identified in the scope of the Report. Any cost advice provided verbally or in this report must be taken as of a general nature and is not to be relied on. Actual costs depend on the quality of materials, the standard of work, what price a contractor is prepared to do the work for and may be contingent on approvals, delays and unknown factors associated with third parties. No liability is accepted for costing advice.