



Building and Timber Pest Inspection Report

Inspection Date: Tue, 3 Mar 2026

Property Address: 2 Cloud Cl, Redan VIC 3350, Australia



Contents

	The Parties
Section A	Results of inspection - summary
Section B	General
Section C	Accessibility
Section D	Significant Items
Section E	Additional comments
Section F	Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report has been prepared in accordance with the pre-inspection agreement in place between the parties set out below, which set out the purpose and scope of the inspection, and the significant items that will be reported on. This Report reflects the opinion of the inspector based on the documents that have been provided. This Report should be read in its entirety and in the context of the agreed scope of Services. If there is a discrepancy between the summary findings and the body of the Report, the body of the Report will prevail. We recommend that you should promptly implement any recommendation or advice in this Report, including recommendations of further inspections by another specialist. If you have any queries with this Report or require further information, please do not hesitate to contact the person who carried out the inspection. This Report contains reference to material that is the copyright of Standards Australia reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

Original Inspection Date: Tue, 3 Mar 2026

Modified Date: Wed, 4 Mar 2026

The Parties

Name of the Client:

Name of the Principal(if Applicable):

Job Address: 2 Cloud Cl, Redan VIC 3350, Australia

Client's Email Address:

Client's Phone Number:

Consultant: Barry Hasturk Ph: 0419 200 040
Email: Niddrie@jimsbuildinginspections.com.au

Company Name: Jim's Building Inspections Niddrie

Company Address and Postcode: Oaklands Junction 3063

Company Email: Niddrie@jimsbuildinginspections.com.au

Company Contact Numbers: 0419 200 040

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors

The following apply: The property is also known as 2/821 Darling St Redan.

Section A Results of Inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
Safety Hazard		✓
Major Defect	✓	
Minor Defect	✓	
Live Timber Pest Activity		✓
Timber Pest Damage		✓
Conditions Conducive to Timber Pest Activity	✓	
Evidence of fungal decay activity and/or damage	✓	
Evidence of wood borer activity and/or damage		✓
Evidence of a previous termite management program		✓

Overall Condition (Building)

In summary, the building, compared to others of similar age and construction is in fair condition with some major and minor defects found.

Overall Condition (Timber Pest)

In summary, the building, compared to others of similar age and construction is highly susceptible to timber pests. A termite treatment is required.

Section B General

General description of the property

Building Type	Unit, Residential
Company or Strata title	Yes
Floor	Slab on ground
Furnished	Unfurnished
No. of bedrooms	2
Occupied	Unoccupied
Orientation	West
Other Building Elements	Driveway, Garage, Party Walls, Fence - Fabricated Metal Fence, Porch, Water Tanks
Other Timber Bldg Elements	Architraves, Door Frames, Internal Joinery, Doors, Landscaping Timbers and Construction, Porch / Patio, Skirting Boards, Fascias, Veranda Posts
Roof	Tiled, Pitched
Storeys	Single
Walls	Brick Veneer
Weather	Overcast

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Fencing
- Exterior
- Interior
- Gardens
- Roof Exterior - Part
- Landscaping Timbers
- Roof Void - Part
- Posts
- The Site
- Wall Exterior

The inspection excludes areas which are affected by obstructions, where access is limited or unsafe. We do not move obstructions and defects, timber pest activity or conditions conducive to these may not be obvious unless they are removed.

Inaccessible Areas

The following areas were inaccessible:

- Areas of low roof pitch preventing full inspection.
- Ceiling Cavity - Part.
- Roof Exterior - Part
- Slab edge which would normally be exposed due to finished ground levels obscuring inspection.
- Wall Exterior - where neighbouring buildings immediately adjoin.

Any areas which are inaccessible at the time of inspection present a high risk for undetected defects and timber pest activity and conditions conducive to these. The client is advised to make inaccessible areas accessible wherever possible for re-inspection.

Obstructions and Limitations

Building defects, termite and timber pest activity as well as conditions conducive to both, may be concealed by the following obstructions which prevented full inspection:

- Appliances and equipment
- Above safe working height
- Areas of low roof pitch preventing full inspection
- Duct work
- Ceiling linings
- External concrete or paving
- External finished ground level
- Degree of roof incline too steep for safe access
- Fixed Furniture - Built-in Cabinetry
- Fixed ceilings
- Floor coverings
- Insulation
- Landscaping
- Patio
- Porch
- Roofing material is a slip hazard - not safe to access
- Stored items
- Unsafe to Access Roof - No Fall Protection System
- Wall linings

The presence of obstructions increases the risk of undetected building defects, timber pest activity and conditions conducive to these. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas urgently.

Undetected defect risk (Building)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: **High**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Undetected defect risk (Timber Pest)

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection

The risk of undetected defects is: **High**

When the risk of undetected defects is medium or high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

Safety Hazard

No evidence was found

Major Defect

Finding 2.01

Building: Main Building
Location: All Tiled Areas > All Areas
Finding: Elevated Moisture Levels – Floor Tiled Areas (Major Defect)
Information: Elevated moisture readings ranging from approximately 60% to 100% were detected using a moisture meter to all floor tiled areas within the dwelling. The elevated readings were consistent across the tiled areas. Minor moisture-related swelling was observed to the bathroom door jamb, which is consistent with prolonged exposure to moisture.

No active water leaks were identified during the inspection. It should be noted that running water was not available at the time of inspection, which limited the ability to fully test plumbing fixtures and wet areas. Moisture testing of adjoining carpeted areas did not reveal elevated readings, suggesting that the moisture appears to be largely confined to the tiled areas.

The source of the elevated moisture readings could not be determined at the time of inspection. Possible causes may include historical water leaks, a concealed plumbing leak beneath the slab or within wall cavities, failure of waterproofing in wet areas, or excessive wet mopping practices. Regardless of the cause, the presence of widespread elevated moisture readings indicates a potential underlying issue.

In accordance with the principles of AS 4349.1–2007, widespread elevated moisture affecting multiple floor areas and having the potential to cause deterioration of building elements is considered a Major Defect, as it may lead to concealed damage to floor substrates, wall framing, skirting boards and other structural or finish elements if left unaddressed.

Recommendation:

It is recommended that further investigation be undertaken by a licensed plumber or leak detection specialist to determine the source of the moisture. This may involve pressure testing of plumbing systems and potential invasive inspection. Once the source is identified, appropriate rectification should be undertaken and affected building elements repaired as required.

Time Frame:

Further investigation recommended in the short term due to the extent of elevated moisture readings and potential risk of concealed damage.







Minor Defect

Finding 3.01

Building:	Main Building
Location:	All Areas > All Areas
Finding:	External Defects – Porch Posts, Eaves, Roof Tiles and Roof Plumbing
Information:	The following external defects were observed during the inspection:

Weathered and deteriorating timber posts were noted to the front porch area. Prolonged exposure to weather without adequate maintenance may lead to further deterioration and potential loss of structural integrity over time.

Loose quad mouldings were observed beneath sections of the eave lining. Loose trim elements may allow minor gaps where moisture, insects or debris can enter.

Minor cracking was observed to roof tiles in several locations. No evidence of active water leaks was detected internally at the time of inspection. Cracked roof tiles, however, may allow moisture ingress during heavy rain if deterioration progresses.

A downpipe and spreader from the main roof was observed discharging onto the porch roof flashing. Direct discharge of concentrated water flow onto flashing components is considered poor roof plumbing practice and increases the risk of water

tracking beneath roof coverings and into the building envelope.

Recommendation:

It is recommended that the front porch timber posts be assessed and repaired or replaced as required, and that appropriate sealing or protective coating be applied. Loose quad mouldings should be refixed. Cracked roof tiles should be replaced to maintain roof integrity. A licensed roofing plumber should assess the downpipe discharge arrangement and redirect the flow to an appropriate drainage point that does not rely on flashing to manage concentrated water discharge.

Time Frame:

Rectification recommended in the short to medium term to prevent further deterioration and reduce risk of moisture ingress.





Finding 3.02

Building:	Main Building
Location:	All Areas > All Areas
Finding:	Minor Internal Defects – Garage, Doors, Flooring and Joinery
Information:	The following minor internal defects were observed during the inspection:

Staining was observed to the garage concrete floor, suspected to be oil stains likely associated with vehicle parking. Moisture-related damage was noted around the external garage door handle area. Scuffs, marks and minor damage were observed to the plaster walls within the garage.

In the main bathroom, the tile skirting was observed to be partially separating from the

wall. Minor crack damage was observed to the front bedroom door.

The carpet to the rear bedroom was worn, and the carpet to the living area was damaged with fraying observed along the edges. These defects are consistent with normal wear and tear over time.

The timber door seal to the main entry door was weathered. The entry door was also observed to be binding during operation, making it difficult to open and close. Minor cosmetic damage was observed to the edge of the entry door.

Additional minor cosmetic defects included paint damage to the hallway sliding door and a damaged door catch to the cupboard door located across from the kitchen.

Recommendation:

It is recommended that damaged or worn flooring be repaired or replaced as required. The tile skirting in the bathroom should be re-secured. The entry door should be adjusted to allow smooth operation and the weather seal replaced if necessary. Minor plaster and paint defects may be repaired as part of general maintenance.

Time Frame:

Maintenance recommended in the short to medium term.







Weathered timber sill




Binding entry door



Damaged door



Damaged carpet





Live Timber Pest Activity

No evidence was found

Timber Pest Damage

No evidence was found

Conditions Conducive to Timber Pest Activity


Finding 6.01



Building:	Main Building
Location:	All tiled areas > All Areas
Finding:	Elevated moisture levels to kitchen, bathroom, hallway, entry, laundry & toilet floor tiles (TP)
Information:	At the time of inspection, elevated moisture readings were detected using a moisture meter in the kitchen, bathroom, hallway, entry, laundry & toilet floor tiles. Levels of moisture ranged from 60% to 100% in some areas. No active water leaks were observed during the inspection. It is important to note that no running water was available during the inspection. Moisture readings in adjoining rooms were normal. It appears that the moisture is contained to these tiled areas only. Some moisture

damage was found to the bathroom door jamb suggesting moisture is affecting surrounding building elements in this area however no other moisture damage was observed to skirting boards, door jambs, architraves or joinery. It is suspected that the moisture may be from conditions such as excessive wet mopping, spills, or historic overflows or leakages from appliances or plumbing fixtures.

In accordance with AS 3660.2, wet areas and plumbing-related moisture issues are recognised as increasing termite risk, as persistent dampness within building elements can create conditions conducive to termite activity and concealed access. Ongoing moisture exposure may also lead to deterioration of surrounding materials, further elevating termite susceptibility.

As a result, the moisture issues identified within these areas are considered to increase the risk of termite activity and material deterioration. It is recommended that these areas are periodically monitored for ongoing moisture issues. Assessment is recommended by a licensed termite management or pest control contractor where elevated termite risk is identified.







Finding 6.02

Building:	Main Building
Location:	All Areas > All Areas
Finding:	Inground timber contact (TP)
Information:	At the time of inspection, in-ground timber contact was observed to the front and rear yards, including timber garden edging under fence panels all in direct contact with the ground. There was also a dead tree stump next to the water tank. These timber elements are positioned within the soil zone and in close proximity to the building and associated structures.

In accordance with AS 3660.2, conditions that facilitate termite access or provide a direct food source are recognised as increasing the risk of termite activity to existing buildings. Timber elements in direct contact with the ground are particularly vulnerable, as they can attract subterranean termites and support concealed foraging activity, potentially allowing termite colonies to establish and migrate toward nearby structures without early detection.

As a result, the presence of in-ground timber elements is considered to increase the risk of termite activity to the property. It is recommended that a licensed termite management or pest control contractor be engaged to assess these conditions and provide advice on appropriate risk mitigation measures, which may include removal or replacement of timber elements with non-susceptible materials, isolation of timber from soil contact, and integration of suitable termite management measures to suit the

existing site conditions.



Finding 6.03

Building:	Main Building
Location:	All Areas > All Areas
Finding:	Slab edge - concealed (TP)
Information:	At the time of inspection, the slab edge to most areas of the building was observed to be concealed behind concrete paving and landscaping. This condition restricts clear visibility of the slab perimeter and limits the ability to visually inspect critical inspection zones intended for the early detection of termite activity.

Where slab edges and inspection zones are concealed, concealed termite entry paths may develop without early warning. In accordance with AS 3660.2, existing buildings are required to maintain conditions that allow for effective inspection and management of termite risk, noting that obstructions such as paving, paths, or landscaping can compromise the effectiveness of termite management measures. Where inspection zones are obstructed, the likelihood of undetected termite activity is increased.

As a result, the current configuration is considered to increase the risk of concealed termite entry to the building. It is recommended that a licensed termite management or pest control contractor be engaged to assess the extent of the concealed slab edges and provide advice on rectification options, which may include modifying paving or

landscaping to reinstate suitable inspection access and integrating appropriate termite management measures to suit the existing conditions.



Finding 6.04

Building:	Main Building
Location:	Walls > Rear Left
Finding:	Uncontrolled discharge from hot water unit (TP)
Information:	At the time of inspection, the hot water unit located to the rear of the building was observed to have an overflow pipe discharging directly onto the ground, rather than being connected to a suitable drainage system. This condition allows ongoing moisture to accumulate at the base of the building and surrounding soil.

Conditions that promote persistent dampness or poor drainage around a building are recognised as conducive to termite activity, as elevated moisture levels can attract subterranean termites and support concealed foraging activity. Uncontrolled discharge from hot water system overflows may therefore increase moisture-related deterioration and termite risk.

As a result, the discharge from the air conditioner unit overflow is considered to contribute to conditions conducive to termite activity. It is recommended that a licensed plumber be engaged to connect the overflow pipe to an appropriate drainage point, ensuring that water is not discharged directly onto the ground adjacent to the

building, with further advice from a licensed termite management or pest control contractor where elevated termite risk is identified.



Finding 6.05

Building:	Main Building
Location:	Roof Exterior > All Areas
Finding:	Organic growth on roof (TP)
Information:	At the time of inspection, organic growth was observed to the roof areas. These conditions promote prolonged moisture retention and the potential for blockage of roof drainage, the issue is suspected to be associated with a lack of routine maintenance.

In accordance with AS 3660.2, conditions that promote ongoing dampness and moisture accumulation are recognised as increasing termite risk to existing buildings, as elevated moisture levels can create environments conducive to termite foraging and concealed activity. The potential for blocked gutters and downpipes may allow water to overflow or discharge against building elements, increasing moisture exposure to adjacent materials and reducing the effectiveness of termite risk management through visual inspection.

As a result, the observed organic growth are considered to increase moisture-related deterioration and elevate the overall risk of termite activity. It is recommended that an appropriately qualified roof plumber be engaged to clean and service the gutters and downpipes and that roof surfaces be maintained to reduce moisture retention, with ongoing monitoring and advice from a licensed termite management or pest control contractor where elevated termite risk is identified.



Finding 6.06

Building:	Main Building
Location:	Meter Box > All Areas
Finding:	Termite management system - no evidence of chemical installation (TP)
Information:	At the time of inspection, there was no visible evidence to suggest that a chemical termite management system has been installed or remains effective. In addition, no durable notice was observed within the electrical switchboard to identify the presence, type, or date of any termite protection measures.

In the absence of identifiable termite management measures to the building perimeter, slab penetrations, or accessible inspection zones, the dwelling cannot be confirmed as having an active termite management system. Where termite protection cannot be verified, the building is considered to be at an increased risk of termite activity.

In accordance with AS 3660.2, where no termite management system is present to an existing building, the risk of concealed termite entry and infestation is significantly increased, as subterranean termites may gain access to timber building elements without early detection.

For this reason, the installation of a post-construction chemical termite management system is highly recommended to reduce the risk of termite activity. A durable notice should also be installed within the electrical switchboard to clearly identify the treatment provided and support ongoing inspection and maintenance.

Engagement of a licensed termite management or pest control contractor is recommended as a matter of priority to assess the site conditions, consider local termite risk, and determine the most appropriate treatment method and procedures for this property.



Finding 6.07

Building:	Main Building
Location:	All Areas > All Areas
Finding:	Subterranean termite management proposal (TP)
Information:	No live termite activity was found during the inspection of the property. However,

based on the inspection findings, it is recommended that a comprehensive subterranean termite management program be implemented in accordance with AS 3660.2 (Termite management – In and around existing buildings and structures). The inspection identified several conditions that increase termite risk, including the absence of a verifiable termite management system, elevated moisture levels to internal tiled areas, concealed slab edges, moisture-retaining landscaping elements, in-ground timber contact, and deteriorated timber decay.

It is proposed that a licensed termite management contractor undertake a detailed site assessment to determine the most appropriate post-construction termite management solution for the property, taking into account local termite pressure, soil conditions, building configuration, and existing obstructions. This assessment should inform the installation of a suitable chemical soil treatment or alternative approved management system designed to reduce the risk of concealed termite entry to the structure.

The proposed works should also include recommendations to improve ongoing termite risk management, such as reinstating or improving inspection access where practicable, managing moisture sources, addressing in-ground timber contact, and installing a durable notice within the electrical switchboard to clearly document the type and date of any termite treatment applied. Ongoing inspections and maintenance should be scheduled in accordance with the contractor's advice to ensure the long-term effectiveness of the termite management strategy and continued protection of the building.

Evidence of fungal decay activity and/or damage

Finding 7.01

Building:	Main Building
Location:	All Areas > All Areas
Finding:	Timber decay & rot - Conducive conditions (TP)
Information:	At the time of inspection, evidence of timber decay at varying stages was observed to the timbers under fence panels, fascia board on front porch, and dead tree stump next to water tank.

These conditions are suspected to have developed over time due to prolonged moisture exposure and a lack of appropriate timber maintenance, allowing moisture ingress and decay to progress within the timber elements. In accordance with AS 3660.2, deteriorated and moisture-affected timber is recognised as increasing the risk of termite activity, as decayed timber can attract termites and may provide concealed access or harbourage, particularly where defects are obscured by finishes such as paint.

As a result, these condition are considered to present an elevated risk of ongoing

deterioration and potential termite susceptibility. It is recommended that an appropriately qualified builder or carpenter be engaged to further assess the extent of timber decay, remove any concealed deteriorated material, and undertake suitable repairs or replacement, with consideration also given to advice from a licensed termite management or pest control contractor where termite risk is identified.





Evidence of wood borer activity and/or damage

No evidence was found

Section D Significant Items

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed

- As identified in summary and defect statements
- Termite and Timber Pest Technician / Licensed Pest Controller

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

- The property is a single-storey, two-bedroom unit forming part of a unit complex and is suspected to be approximately 15 years old (age not verified). The building is constructed on a concrete slab with brick veneer walls and a pitched roof with roof tiles and includes a single garage. When compared with buildings of similar age and construction type, the property was found to be in fair condition, with a mixture of minor maintenance items and one significant moisture-related issue identified during the inspection.

□

Major Defects

- Elevated Moisture to Internal Floor Tiled Areas:

Elevated moisture readings ranging between approximately 60% and 100% were detected across all internal floor tiled areas using a moisture meter. Minor moisture-related swelling was also observed to the bathroom door jamb. No active leaks were identified at the time of inspection, however running water was not available during the inspection which limited plumbing testing.

The source of the moisture could not be determined and may be related to historical water leaks, concealed plumbing leaks beneath the slab or within wall cavities, waterproofing issues, or excessive wet cleaning practices. Due to the widespread nature of the elevated readings and potential for concealed damage, this condition is considered a Major Defect and requires further investigation.

□

Minor Defects

- Weathered and deteriorating timber posts to the front porch.
- Loose quad mouldings beneath eave linings.
- Minor cracking to roof tiles (no internal leaks detected at the time of inspection).
- Downpipe and spreader from the main roof discharging onto porch roof flashing (poor roof plumbing practice).
- Staining to garage concrete floor (suspected oil stains).
- Moisture damage around external garage door handle.

- Scuffs and damage to garage plaster walls.
- Tile skirting partially detached in the main bathroom.
- Minor crack damage to front bedroom door.
- Worn carpet to rear bedroom and damaged/fraying carpet in living area.
- Weathered timber door seal to entry door.
- Entry door binding during operation.
- Minor cosmetic damage to entry door edge.
- Paint damage to hallway sliding door.
- Damaged cupboard door catch adjacent to kitchen.

□

Termite and Timber Pest

No live termite activity or termite damage was identified during the inspection. No evidence of a termite management system or durable notice was observed on the property.

Several conducive conditions for termite and timber pest activity were identified, including:

- Timber fungal decay and rot beneath fence panels.
- Decaying dead tree stump.
- Timber decay to fascia around the front porch.
- Elevated moisture levels within internal tiled areas.
- In-ground timber contact.
- Concealed slab edges around the building perimeter.
- Uncontrolled discharge from the hot water unit.
- Organic growth observed on roof surfaces.

Although no active infestation was detected, the presence of moisture and decaying timber elements increases the long-term risk of termite activity.

□

Inspection Limitations

This inspection was visual and non-invasive in nature in accordance with AS 4349.1. Concealed areas including wall cavities, plumbing beneath slabs, waterproofing membranes, and underground services could not be inspected. Moisture meter readings are indicative only and may vary depending on material composition and environmental conditions. Running water was not available at the time of inspection, which limited the ability to fully test plumbing fixtures and wet areas. No destructive testing was undertaken.

□

Overall Assessment

The property generally presents as typical for a unit of its age; however, the elevated moisture readings across internal tiled areas represent the most significant issue and require further investigation by a licensed plumber or leak detection specialist. Addressing moisture issues, improving drainage conditions, and rectifying termite conducive conditions will assist in preserving the building and reducing future risk.

For further information, advice and clarification please contact Barry Hasturk on: 0419 200 040

Section D Significant Items


The following items were noted as - For your information


Noted Item

Building: Main Building
Location: All Areas > All Areas
Finding: Additional Photos - Obstructions and Limitations
Information: These photographs are an indication of the obstructions and limitations which impeded full inspection of the property at the time of inspection. These obstructions can hide an array of defects and should be removed to allow full inspection to be carried out. A re-inspection is recommended once the areas are made accessible.














Noted Item

Building: Main Building
 Location: All Areas > All Areas
 Finding: Additional Photos
 Information: Additional photos are provided for your general reference

















Noted Item


Building: Main Building
Location: All Areas > All Areas
Finding: Termite investigation techniques (TP)
Information: All accessible areas of the dwelling were inspected, with particular attention paid to wet areas, which were closely assessed for elevated moisture levels and temperature anomalies that may indicate conditions conducive to termite activity.




In an attempt to identify concealed or hidden timber pest activity, a range of inspection techniques were adopted. These included the use of a moisture meter to assess susceptible areas, sounding of timber elements using a handheld probing device, and visual assessment of materials for signs commonly associated with termite activity. These signs include moisture-related deterioration, deformation of timber, termite mud leads or bridging, and irregular or regular shaped holes within timber elements that may indicate pest-related damage.

It is noted that termite activity can generate increased moisture and localized temperature variations, and where such irregularities are detected, further investigation may be warranted. However, it is also acknowledged that certain obstructions, including floor coverings, wall linings, wall tiles, and fixed cabinetry such as bathroom fit-offs, can conceal termite activity and limit the effectiveness of visual inspection. As a result, the absence of visible evidence at the time of inspection does not eliminate the possibility of concealed termite activity within inaccessible or obstructed areas of the building.











Definitions to help you better understand this report

Access hole (cover)	An opening in flooring or ceiling or other parts of a structure (such as service hatch, removable panel) to allow for entry to carry out an inspection, maintenance or repair.
Accessible area	An area of the site where sufficient, safe and reasonable access is available to allow inspection within the scope of the inspection.
Appearance defect	Fault or deviation from the intended appearance of a building element.
Asbestos-Containing Material (ACM)	Asbestos-containing material (ACM) means any material or thing that, as part of its design, contains asbestos.
Building element	A portion of a building that, by itself or in combination with other such parts, fulfils a characteristic function. NOTE: For example supporting, enclosing, furnishing or servicing building space.
Client	The person or other entity for whom the inspection is being carried out.
Conditions Conducive to Termite Activity	Noticeable building deficiencies or environmental factors that may contribute to the presence of Termites.
Defect	Fault or deviation from the intended condition of a material, assembly, or component.
Detailed assessment	An assessment by an accredited sampler to determine the extent and magnitude of methamphetamine contamination in a property.
Inspection	Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a reliable conclusion as to the condition of the building.
Inspector	Person or organisation responsible for carrying out the inspection.
Instrument Testing	Where appropriate the carrying out of Tests using the following techniques and instruments: (a) electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements (b) stethoscope - an instrument used to hear sounds made by termites within building elements (c) probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g. bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees and (d) sounding - a technique where timber is tapped with a solid object. (e) T3I - an instrument used to detect movement, moisture and changes in temperature within timber
Limitation	Any factor that prevents full or proper inspection of the building.
Major defect	A defect of sufficient magnitude where rectification has to be carried

	out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
Methamphetamine	An amphetamine-type stimulant that is highly addictive. Methamphetamine is a controlled substance, classified as a Class A (very high-risk) drug under the Misuse of Drug Act. This term is used as a grouping term to include all substances screened for, specifically: Ephedrine, Pseudoephedrine, Amphetamine, Methamphetamine, MDA and MDMA.
Methamphetamine contamination	A property or part of a property where the level of methamphetamine has been tested in accordance with this standard and found to exceed 0.5 micrograms/100 cm ² (Residential) or 10 micrograms/100 cm ² (Commercial).
Methamphetamine production/manufacture	The manufacture of methamphetamine, including processing, packaging, and storage of methamphetamine and associated chemicals.
Minor defect	A defect other than a major defect.
Roof space/Roof void	Space between the roof covering and the ceiling immediately below the roof covering.
Screening assessment	An assessment by a screening sampler to determine whether or not methamphetamine is present.
Serviceability defect	Fault or deviation from the intended serviceability performance of a building element.
Significant item	An item that is to be reported in accordance with the scope of the inspection.
Site	Allotment of land on which a building stands or is to be erected.
Structural defect	Fault or deviation from the intended structural performance of a building element.
Structural element	Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.
Subfloor space	Space between the underside of a suspended floor and the ground.
Subterranean Termite Management Proposal	A written proposal in accordance with Australian Standard AS 3660.2 to treat a known subterranean termite infestation and/or manage the risk of concealed subterranean termite access to buildings and structures.
Termites	Wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.
Tests	Additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be

particularly susceptible to attack by Termites. Instrument Testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.

Timber Pest Activity	Tell-tale signs associated with 'active' (live) and/or 'inactive' (absence of live) Timber Pests at the time of inspection.
Timber Pest Attack	Timber Pest Activity and/or Timber Pest Damage.
Timber Pest Damage	Noticeable impairments to the integrity of timber and other susceptible materials resulting from an attack by Timber Pests.
Urgent and Serious Safety Hazards	Building elements or situations that present a current or immediate potential threat of injury or disease to persons.

Terms on which this report was prepared

This report is based on the condition of the property at the time of inspection. We strongly recommend re-inspection 30 days after this report is issued as the general condition of the property is likely to have changed, including the extent of defects described and instance of potential undetected defects.

This report has been prepared in accordance with and subject to the pre-inspection agreement in place between the parties, which forms part of this Report.

This Report is prepared for the client identified above and may not be relied on by any other person without our express permission or by the purchase of this Report on our website.

SPECIAL ATTENTION SHOULD BE GIVEN TO THE SCOPE, LIMITATIONS AND EXCLUSIONS IN YOUR PRE-INSPECTION AGREEMENT AND THIS REPORT

Any of the exclusions or limitations identified for this Report may be the subject of a special-purpose inspection which we recommend being undertaken by an appropriately qualified inspector

RELIANCE AND DISCLOSURE

This report has been prepared based on conditions at the time of the report.

We own the copyright in this report and may make it available to third parties.

If your Property is in the Australian Capital Territory, you acknowledge we will make certain information about this Report available to the ACT Government for inclusion in the building and pest inspections public register if required under the *Civil Law (Sale of Residential Property) Act 2003*. This will include the fact the report has been prepared, the Property street address, date of the inspection, the name of the person who prepared the report and (if applicable) the entity that employs them.

UNDETECTED DEFECT RISK RATING

If this Report has identified a medium or high-risk rating for undetected defects, we strongly recommend a further inspection of areas that were inaccessible. This may include an invasive inspection that requires the removal or cutting of walls, floors or ceilings.

If the Property has been vacant for a period of time, moisture levels or leaks may not be detectable at the time of the inspection because often only frequent use of water pipes (showers, taps etc) result in a leak being identifiable. We advise further testing on pipes and water susceptible areas (such as the bathroom and laundry) after more frequent use has occurred.

IMPORTANT SAFETY INFORMATION:

This is not a report by a licensed plumber or electrician. We recommend a special-purpose

report to detect substandard or illegal plumbing and electrical work at the Property

This is not a smoke alarm report. We recommend all existing detectors in the Property be tested and advice sought as to the suitability of number, placement and operation.

This is not an asbestos report. There are potential products in the Property containing asbestos that will not be identified in this report. In order to accurately identify asbestos, we recommend performing an asbestos inspection, particularly for buildings built prior to 1988.

This is not a report on safety glass. Glazing in older homes may not reflect current standards and may cause significant injury if damaged. Exercise caution around the glass in older homes.

This is not a report on window opening restrictions. We have not inspected window opening restrictors. Window openings in older buildings may not reflect current standards and can be a potential risk. Window opening restrictors are advised for all second story or above windows with sill heights below 900mm. Some states make this a mandatory requirement. Owners should enquire of their local and state requirements to ensure compliance.

This is not a report on pool safety. If a swimming pool is present it should be the subject to a special purpose pool inspection.

External Timber Structures - Balcony and Decks. It is strongly recommended that a Structural Engineer is required to assess distributed load capacity of external timber structures such as balconies and decks, alerting users of the load capacity. Regular maintenance and inspections by competent practitioners to assess the ongoing durability of exposed external timber structures are needed.

This is not a Group Titled Property Report as per AS4349.2. If you require a report for a Group Titled Property as per this standard, please seek a separate inspection for Group Titled Properties.

MOISTURE

The identification of moisture, dampness or the evidence of water penetration is dependent on the weather conditions at the time an inspection. The absence of dampness identified in this Report does not necessarily mean the Property will not experience some damp problems in other weather conditions or that roofs, walls or wet areas are watertight.

Where the evidence of water penetration is identified we recommend detailed investigation of waterproofing in the surrounding area monitoring of the affected area over a period of time to fully detect and assess the cause of dampness.

MAINTENANCE OF THE PROPERTY

This Report is not a warranty or an insurance policy against problems developing with the Property in the future. Accordingly, a preventative maintenance program should be implemented which includes systematic inspections, detection and prevention of issues. Please contact the inspector who carried out this inspection for further advice.

It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of

conditions conducive to timber pest activity. Undertaking thorough regular inspections at intervals not exceeding twelve months (or more frequent inspections where the risk of timber pest attack is high or the building type is susceptible to attack). To further reduce the risk of subterranean termite attack, implement a management program in accordance with Australian Standard AS3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical barrier. However, AS3660 stresses that subterranean termites can bridge or breach barrier systems and inspection zones and those thorough regular inspections of the building are necessary.

NO CERTIFICATION

- a) The Property has been compared to others of a similar age, construction type and method that had an acceptable level of basic maintenance completed.
- b) We don't advise you about title, ownership or other legal matters like easements, restrictions, covenants and planning laws. None of our inspections constitutes approval by a Building Surveyor, a certificate of occupancy or compliance with any law, regulation or standard, including any comment on whether the Property complies with current Australian Standards, Building Regulations or other legislative requirements.

RECTIFICATION COSTS

We don't provide advice on the costs of rectification or repair unless specifically identified in the scope of the Report. Any cost advice provided verbally or in this report must be taken as of a general nature and is not to be relied on. Actual costs depend on the quality of materials, the standard of work, what price a contractor is prepared to do the work for and may be contingent on approvals, delays and unknown factors associated with third parties. No liability is accepted for costing advice.